
























Figure 2-2
Cumulative Recovery Of PSH and Groundwater by the RCS
Motiva Enterprises Fairfax Terminal



PSH Recovery per month Groundwater Recovery per Month







12420 Milestone Center Drive Germantown, MD 20876

## Legend

- AS Antiseep Collar Monitoring Well
- DW Deep Interval Monitoring Well
- FL Fence Line Monitoring Well (EPA Installed)
- IP Infiltration Test Piezometer Well
- IW Intermediate Interval Monitoring Well
- MB Mantua Trench Passive Bailer Well
- MD Mantua Trench Depression Well
- MRW Metal Recovery Well
- \* MS Mantua Segmented Trench Monitoring Well
- MW Monitoring Well
- OBW Offsite Observation Well
- ORW Offsite Recovery Well
- OWR Recovery Well (Stockbridge Tovito)
- ▲ P Piezometer Well
- PSL Infiltration Pilot Study Well
- SR Stockbridge Piezometer Well
- TD Tovito Drive Monitoring Well
- RW Recovery Well (Well Barrier)
- RW Recovery Well (North Trench)
- RW Recovery Well (South Trench)
- CH Transmontaigne Property Well (Formerly Global)
- CL Colonial Pipeline Property Well

## $\frac{\text{CH-012}}{\text{ND(0.5)}}$ Well that did not contain detections of Benzene

CH-032 Well that contained detections of Benzene at

3.2 or below the AQWC of 5 ug/L

CH-008 Well that contained detections of Benzene above the AQWC of 5 ug/L

MW-114 Well not sampled

Benzene Isoconcentration Contour

Data From: March 22-25, 2016 Isoconcentration Contours in 5, 50, and 500 ug/L ND(0.5) - Not Detected Above Laboratory Reporting Limits ug/L - Micrograms Per Liter

Figure 2-5 **Benzene Concentrations** March 2016

> **MOTIVA Enterprises Fairfax Terminal**